

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---



Retrouvez dans l'Avid Configuration Guidelines le descriptif détaillé des différentes configurations Matériel / OS / Hardware pour chaque version soft Avid.

Voir aussi au l'article au sujet des nouvelles versions Avid : [\*\*Avid Media Composer & Symphony V6.0 Version 6 disponible au téléchargement chez CTM Solutions !\*\*](#)

For a complete list of qualified systems for the current release see [Avid Qualified Systems for Media Composer 6, Symphony 6, Newscutter 10, Assist 2.5, and Instinct 3.5](#)

### **System Configuration Guidelines for Media Composer 6, Symphony 6 and Newscutter 10**

**System**

**Required for v6/v10**

**Lowest Supported Release**

**Avid Media Composer**

**Avid Symphony**

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

### Avid Newscutter

#### [Dell T5500](#)

Windows 7 64-bit

3.5.4

6.0

7.5.4

#### [Dell T3500](#)

Windows 7 64-bit

3.5.4

6.0

7.5.4

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

### [HP Z800](#)

Windows 7 64-bit

3.5.4

3.5.4 (Nitris DX only)

7.5.4

### [HP Z400 \(Gen 1\)](#)

Windows 7 64-bit

3.5.4 (Vista 64) or 3.5.9 (XP)

6.0

7.5.4 (Vista 64) or 7.5.9 (XP)

### [HP Z400 \(Gen 2\)](#)

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

Windows 7 64-bit

3.5.4 (Vista 64) or 3.5.9 (XP)

6.0

7.5.4 (Vista 64) or 7.5.9 (XP)

[HP Z200 \(Tower\)](#)

Windows 7 64-bit

5.0.3 (Win 7 only)

6.0

9.0.3 (Win 7 only)

[HP Z210](#)

Windows 7 64-bit

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

5.0.3.7r (Win 7 only)

6.0

9.0.3.7r (Win 7 only)

### [Mac Pro Intel \(Westmere\)](#)

Lion v10.7.1 and

v10.7.2

5.0.3

5.0.3

N/A

### [Mac Pro Intel \(Nehalem\)](#)

Lion v10.7.1 and

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

v10.7.2

3.5.1

3.5.1 (Nitris DX only)

N/A

### [Mac Pro Intel \(Harpertown\)](#)

Lion v10.7.1 and

v10.7.2

3.0

3.0 (Nitris DX only)

N/A

### [HP XW8600\\*](#)

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

Windows 7 64-bit

3.0

3.0 (Nitris DX only)

7.0

### [Dell T5400](#)

Windows 7 64-bit

3.0

6.0

7.0

### [Dell T3400](#)

Windows 7 64-bit

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

3.0

6.0

7.0

**System Configuration Guidelines for Media Composer 5.5, Symphony 5.5, Newscutter 9.5 and Ea**

**System**

**Notes**

**Lowest Supported Release**

**Avid Media Composer**

**Avid Symphony**

**Avid Newscutter**

[Dell T5500](#)



## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

No support for Adrenaline or Mojo Analog hardware supplied

3.5.4

NA

7.5.4

[Dell T3500](#)

3.5.4

NA

7.5.4

[HP Z800](#)

See Answer [290045](#) regarding OS and Avid DNA hardware support in v4.0.

3.5.4

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

3.5.4 (Nitris DX only)

7.5.4

[HP Z400 \(Gen 1\)](#)

3.5.4 (Vista 64) or 3.5.9 (XP)

NA

7.5.4

[HP Z400 \(Gen 2\)](#)

3.5.4 (Vista 64) or 3.5.9 (XP)

NA

7.5.4

[HP Z200 \(Tower\)](#)

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

5.0.3 (Win 7 only)

NA

9.0.3

[HP Z210](#)

Requires PCI 1394 controller for Firewire connectivity

5.0.3.7r (Win 7 only)

NA

9.0.3.7r

[Mac Pro Intel \(Westmere\)](#)

64-bit Kernel is not supported. See [Article 3375771](#) for more details.

5.0.3

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

5.0.3

9.0.3

### [Mac Pro Intel \(Nehalem\)](#)

3.5.1

3.5.1 (Nitris DX only)

7.5.1

### [Mac Pro Intel \(Harpertown\)](#)

3.0

3.0 (Nitris DX only)

7.0

### [Mac Pro Intel](#)

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

3.0

NA

7.0

[HP XW8600\\*](#)

3.0

3.0 (Nitris DX only)

7.0

[HP XW8400 Dual Quad Core](#)

2.7

1.5

6.7

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

### [HP XW8400 Dual Dual Core](#)

2.2.10

1.6

6.2.10

### [HP XW9300](#)

NA

1.0

NA

### [HP XW8200](#)

No Vista Support

2.0

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

1.0

6.0

[HP XW8000](#)

No 3.x / 7.x + Support

2.7 and lower

NA

6.7 and lower

[HP XW4600](#)

2.7

NA

6.7

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

### [Dell Precision 490](#)

3.0

NA

7.0

### [Dell T5400](#)

3.0

NA

7.0

\*For more information on the XW8600, see this link: [269151](#)

### **November 3, 2011:**

- Added systems supported for MC 6, SY 6 and NC 10



## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

### May 18th, 2011:

- The following guides were updated:
  - HP z800 to Rev H
  - HP z400 Gen 1 to Rev G
  - HP z400 Gen 2 to Rev G
  - HP XW8600 to Rev H
- 
- Updates include:

Updated HP guides to reflect suggested BIOS settings when working with USB audio I/O devices. Avid suggests disabling Intel Turbo Boost Technology when working with such devices; for more information see this KB article: [Audio Pops or Stutters When Played Through USB Audio Devices \[408451\]](#)

- 
- Z-series guides were updated with a new supported BIOS (non-mandatory) and Win 7 SP1 support
- XW8600 guide was updated for ISIS 3.2 support. The Intel PRO 1000 PT and PF must be moved to a different slot of one particular configuration

### April 22, 2011:

- The following guides were updated:
- Dell T3400 to Rev C
- Dell T5400 to Rev E
- Dell T5500 to Rev E
- Mac Pro Nehalem to Rev D
- Mac Pro Westmere to Rev B

## **Rappel : Avid Configuration Guidelines and Slot Configurations**

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

### **March 25th, 2011:**

- Updated HP z400s to Rev F, z800 to Rev G, and XW8600 to Rev G
- Clarified storage arrays supported on embedded SAS controllers
- Added support for StudioRAID 5Ti

### **March 15th, 2011:**

- Added HP z200

### **March 8th, 2011:**

- Updated z800, XW8600, z400 to support AJA Io Express
- Updated z400 Gen 2 to support NVIDIA Quadro FX 2000

### **November 29th, 2010:**

- Updated Unity MediaNet support on the Dell T3500

### **September 27th, 2010:**

- Added support for the HP z400 Single 3.33 6-Core system

### **September 24th, 2010:**

- Added support for the new MacPro dual 2.66 GHz 6-Core Intel "Westmere"

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

### August 27th, 2010:

- Updated the HP z800 guide to Rev E, which includes the 6-core systems

### June 9th, 2010:

- For information about configurations that are not longer supported with Media Composer 5, NewsCutter 9, and Symphony 5, please see this article: [A Configurations that are No Longer Supported with Media Composer 5, Symphony 5, and NewsCutter 9 \[366737\]](#)
- Updated the HP XW8600 guide to Rev E1.
- Updated the HP Z800 guide to Rev D1
- Updated the HP Z400 Gen 1 guide to Rev D1
- Updated the HP Z400 Gen 2 guide to Rev B1

### May 28th, 2010:

March 25th, 2010: Updated the HP Z400 Gen2 guide to Rev A1. Included support for the Quad-Core Xeon 2.93GHz 8MB cache W3540 Processor

March 9th, 2010: Updated the HP Z800 Guide. Added Gen2 HP Z400 Guide and updated the Gen1 HP Z400 Guide. To determine whether you have a Gen1 or Gen2 HP Z400, consult this document: [Avid Professional Video Support for New Gen2 HP z400 CPUs \[351671\]](#)

January 27th, 2010: Updated the Dell T5500, T5400, and T3500 guides with information about Unity MediaNet connectivity.

September 23rd, 2009: Updated to include the Dell T5500 and T3500 configuration guides. Updated z400 and z800 configuration guide to rev B. Updated to include link for Adrenaline and

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

Windows XP on the Z400 and Z800 platform.

July 21st, 2009: Updated to include the Z800 and Z400 configuration guides.

May 8th, 2009: Updated to include link about XW8600 Support

April 28th, 2009: Updated to include Nehalem MacPro configuration guide

March 17, 2009: Updated Harpertown MacPro configuration guide to rev C

January 29th 2009: Updated Dell T5400 configuration guide to rev B and HP xw4600 to rev E

December 1st 2008: Updated to include the Dell T5400 configuration guide.

November 9th 2008: Updated to include the XW8400 slot config guide for Symphony Nitris.

June 25th 2008: Updated HP xw8600 config guide to rev C and added HP xw4600config guide.

[Dell T3400 slot Guide Rev C.pdf](#)

[Dell T5500 slot Guide Rev E.pdf](#)

[Dell T3500 slot Guide Rev E.pdf](#)

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

[AVID HP Z800 Configuration guide Rev H.pdf](#)

[AVID HP Z400 Gen1 Configuration guide Rev G.pdf](#)

[AVID HP Z400 Gen2 Configuration guide Rev G.pdf](#)

[AVID HP Z200 Configuration guide Rev E.pdf](#)

[MediaComposer 3.0 Dell Precision 490 Configuration Guide.pdf](#)

[MediaComposer 3.0 Mac Pro Intel Pre 2008 Configuration Guide.pdf](#)

[HP\\_xw8400\\_Dual\\_Core\\_Configuration.pdf](#)

[HP\\_xw8400\\_dual\\_quad-core\\_Configuration\\_for\\_Adrenaline\\_and\\_Mojo.pdf](#)

[AVID HP XW8600 Configuration Guide Rev H.pdf](#)

[HP\\_XW8000\\_Configuration\\_Guide.pdf](#)

[HP\\_XW8200\\_Configuration\\_Guide.pdf](#)

## Rappel : Avid Configuration Guidelines and Slot Configurations

Écrit par Josselin Millecamps  
Samedi, 19 Novembre 2011 15:40

---

[XW8400 slot config for Symphony Nitris.doc](#)

[XW9300 Slot Guide for Symphony Nitris.doc](#)

[Dell T5400 slot Guide Rev E.pdf](#)

[HP\\_xw4600 Slot Guide Rev E.pdf](#)

[Mac Pro Intel 2008 harpertown slot guide Rev C.pdf](#)

[Mac Pro Intel 2008 Nehalem slot guide Rev D.pdf](#)

[Mac Pro Intel \(Westmere\)Slot Guide Rev B.pdf](#)