



Mise à jour UltraScope 1.8.2, cette mise à jour logicielle permet d'utiliser simultanément les logiciels UltraScope et Blackmagic Media Express. Elle offre également des améliorations relatives à la performance générale :

Welcome to the UltraScope Software : This software package allows you to set up and update your Blackmagic UltraScope to the latest software release for new features, bug fixes and other enhancements.

### **What's new in UltraScope 1.8.2 :**

#### **General performance and stability improvements**

Ability to run UltraScope and Media Express simultaneously

#### **Minimum system requirements for Mac OS X**

- Mac OS X 10.10 Yosemite
- Mac OS X 10.9 Mavericks or later
- A suitable PCIe slot - PCIe x1 lane cards should work in any slot
- A suitable USB 3.0 port for use with Pocket UltraScope
- 4 GB of system memory recommended
- Note: UltraScope is not supported on Mac Pro G5 computers.

#### **Minimum system requirements for Windows**

- Microsoft Windows 8 64-bit
- Microsoft Windows 7 64-bit
- A suitable PCIe slot - PCIe x1 lane cards should work in any slot
- A suitable USB 3.0 port for use with Pocket UltraScope
- 4 GB of system memory recommended.
- Installing UltraScope Software
- Before installing the software, we recommend that you run "Uninstall UltraScope" first.

The Blackmagic Camera Installer package installs: Blackmagic UltraScope